



Information Bulletin:

Revised ES43 R2-01 Ground Rods at Wood Poles

1.0 Items Covered

ES43 R2-01 R6 Ground Rods at Wood Poles and Multiple Ground Rods

This advisory and the standard listed above can be found at bchydro.com/distributionstandards.

2.0 Overview

ES43 R2-01 has been updated to revision R6. The note to remove the plastics bridges from staples holding the theft deterrent conductor to the pole has been removed as the material has been updated and will no longer have the plastic bridge. A note was added stating the items shown in the figures can be found in ES43 R2-08 *Ground Electrode Installations*.

3.0 Action

ES43 R2-01 R6 is effective immediately.

Designers and Engineers

Designers and engineers shall be aware of the new revision.

Power Line Technicians

Power line technicians shall be aware of the changes and are responsible to apply them.

4.0 Contact

Customer and Customer Representatives

Please direct questions and concerns to your local BC Hydro representative.

BC Hydro Employees and Contractors

Please direct questions and concerns to the author of the standard or to distribution.standards@bchydro.com.

Prepared by: Abdur Rehman	Date: 2026-03-31
----------------------------------	-------------------------